

BUILDING SAFETY CERTIFICATE

Certified that the existing building GG International School, 339/10 (P), Bavdhan Bk, Tal Mulshi, Dist Pune. is having block (s) / Floor(s) as per details below.

Detail Block(s) in School	block (1)
No. of Floor(s) in the Block	Ground Floor + 4 Floor.

The building is owned/occupied by GG International School, 339/10 (P), Bavdhan Bk, Tal Mulshi, Dist Pune. have complied with the Building safety requirements and verified by the officers concerned of Public Works Department Pune on 13/07/2025 in the presence of, Ms Sukhvinder Kaur Principal, GG International School, 339/10 (P), Bavdhan Bk, Tal Mulshi, Dist Pune. and that the building is fit for occupancy for running school with effect from 13/07/2025 for a period of One year


Issued on 15/07/2025 at Pune by


(S.A. Kotkar)

Sub Divisional Engineer,
P. W. Sub Division No.5
Pune-411011.



'Countersigned'


(Dr.S.R. Katkar)

Executive Engineer,
Pune Public Works Division,
Pune-411001.

OW.No./ DB / NOC / 5461 /2025
Office of the Executive Engineer,
Pune Public Works Division, Pune-01.
Date :- 15 JUL 2025

Copy to :- 1 GG International School, 339/10 (P), Bavdhan Bk, Tal Mulshi, Dist Pune.
2. Sub Divisional Engineer, P. W. Sub Division No.5, Pune 411001.